

# GTS



## KMG-T

Force measuring device for testing the forces on the closing edges of automatically operated doors, gates, and barriers

**Operating manual**

# Content

<b>1</b>	<b>Brief Description.....</b>	<b>4</b>
<b>2</b>	<b>About this Manual .....</b>	<b>5</b>
<b>3</b>	<b>For Your Safety .....</b>	<b>6</b>
<b>4</b>	<b>Setup.....</b>	<b>8</b>
<b>5</b>	<b>Force Application.....</b>	<b>9</b>
<b>6</b>	<b>Intended Use.....</b>	<b>10</b>
<b>7</b>	<b>Force-Time Diagram .....</b>	<b>11</b>
<b>8</b>	<b>Operating Mode and Ready to Measure Mode .....</b>	<b>12</b>
<b>9</b>	<b>Key for Operation Instructions .....</b>	<b>13</b>
<b>10</b>	<b>Switching On and Off.....</b>	<b>14</b>
	10.1 Switch On .....	14
	10.2 Switch Off.....	15
<b>11</b>	<b>Display Readings During Measurement.....</b>	<b>16</b>

<b>12</b>	<b>Measurement .....</b>	<b>19</b>
12.1	Process Steps – Easy Mode.....	19
12.2	Process Steps – Extended Mode.....	20
12.3	Measuring Process and Display .....	23
<b>13</b>	<b>Settings.....</b>	<b>27</b>
<b>14</b>	<b>Calibration at GTE Industrieelektronik .....</b>	<b>32</b>
<b>15</b>	<b>KMG-VISION.cloud Service &amp; Evaluation Software.....</b>	<b>33</b>
<b>16</b>	<b>Accessories .....</b>	<b>34</b>
<b>17</b>	<b>Technical Data .....</b>	<b>35</b>

# 1 Brief Description

The KMG-T force tester measures the dynamic and static forces as well as the progression of forces over time on the closing edges of automatically operated doors, gates and barriers.

KMG-T can be used in two different operating modes:

In easy mode, it is a quick and easy-to-use tool for the mandatory annual inspection of doors, gates and barriers in accordance with the technical rules for workplaces like ASR A 1.7 or DHF.

In extended mode, it is used for the detailed inspection of safety in use according to the regulations and standards for quality assurance for manufacturers of doors, gates and barriers or for new installations: with automatic ready to measure mode for repeated measurements and measurement series as well as with manual ready to measure mode for tighter control over the measurement process.

## 2 About this Manual

Read the documentation carefully and familiarize yourself with the operation of the device before using it. Keep this document handy for future reference.

This manual describes how to use the force gauge KMG-T. KMG-T is equipped with a wireless module and therefore deployable with the service tool KMG-VISION.cloud.

### Identification

Display	Meaning	Note
	Note	Offers helpful tips and information
	Objective	Denotes the objectives that is to be achieved via the steps described
	Step	Carry out steps

### **3 For Your Safety**

The following rules must be followed to ensure safe handling of the measuring device.

- ▶ Maintaining product safety/warranty claims
- ▶ Only operate the measuring device within the specifications given in the Technical Data (see chap. 17)
- ▶ Only use the measuring device properly and as intended
- ▶ Do not use force
- ▶ Do not open the measuring device
- ▶ Send in the measuring device for calibration every year (see chap. 14)
- ▶ When not in use, always store the measuring device in the case supplied and protect it from moisture and mechanical shocks
- ▶ The enclosed USB power supply unit must not be operated in damp rooms or outdoor areas.

➤ **Ensure correct disposal**

▶ Send the product to GTE Industrieelektronik GmbH at the end of its service life.

① We will take care of its proper and ecological disposal.



## 4 Setup

1. Measurement surface
2. Display
3. Key
4. USB-C port
5. Handle



For commissioning

- **Remove the display protective film**
  - ▶ Carefully peel off the protective film
- **Charging the battery**
  - ▶ Charge the battery via the USB-C port. A power adapter is included in the case.

## 5 Force Application

During the measuring process, the force must be applied correctly to the measuring surface.

- ➔ **Initiate the measuring process**
- ▶ Switch on the device
- ▶ Apply force vertically and centrally
- ① The measurement starts automatically from a measuring force of 25 N.



## 6 Intended Use

The KMG-T is a compact hand-held device for measuring the progression of forces over time on the closing edges of automatically operated doors, gates, and barriers, according to

- DIN EN 12453
- DIN EN 16005
- DIN EN 16361
- DIN EN 17352
- DIN EN 18650 (withdrawn)
- ASR A 1.7
- DHF protocol TS011 and TS012


The purpose is to check the safety of use of these systems and to ensure quality assurance in accordance with standards during production or annual maintenance.

- ▶ Only use the product for applications for which it was designed.
- ① For the maximum permissible peak force, please refer to the Technical Data (see chapter 17).

## 7 Force-Time Diagram

The KMG-T can measure the following dynamic and static closing forces on doors, gates, and barriers as well as the duration of the force application and displays the following:

$F_d$	maximum dynamic force (permissible peak force)
$F_s$	maximum static force
$T_d$	duration, in which the measured force exceeds 150 N
$F_e$	end force
#ID	measurement ID



## 8 Operating Mode and Ready to Measure Mode

Two different operating modes can be selected for operation:

### **Easy operation mode**

- For maintenance service providers, fitters, tradesmen
- For annual maintenance in accordance with ASR A 1.7
- With quick large display of the maximum force applied

### **Extended operation mode**

- For manufacturers, experts, installers, measuring service providers of door, gate or barrier systems
- In quality assurance

#### **Readiness to measure in the extended mode**

**Automatic:** For quick repeated measurement series at the same place. The device automatically switches to recording mode (REC).

**Manual:** For increased control over the measuring process. The device is initially in readiness to measure before each measurement („Press key“). Only after the key is manually pressed, the device goes into recording mode (REC).

## 9 Key for Operation Instructions

Use the key to navigate through the menus and activate the functions. Depending on how long you press the key, the following is meant:

short	< 3 s
long	> 3 s (in the extended operation mode)
long	> 5 s (in the easy operation mode)

If you press the key for a long while, the device switches off in both cases, i. e. in the easy and in the extended operating mode.

### Navigation:

Select menu item, navigate through the menu	short press
Open submenu	long press
Confirm selection	long press
Exit menu/leave measurement	long press

- ① Selected functions are framed with a rectangle in the submenu.

## 10 Switching On and Off

### 10.1 Switch On

#### ➤ Start the device by pressing the key

▶ Short press	The device starts in the last operating mode used.
▶ Long press (> 3 s)	The device starts and changes the operating mode.

① The operating mode can only be recognized during operation.

## 10.2 Switch Off

- ① Pressing the key continuously for at least 5 seconds switches the device off in any situation.

### Easy mode:

- ▶ Press key > 5 s

### Extended mode:

- ↻ **Exit measurement**
  - ▶ Long press (> 3 s), until the menu display appears.
- ↻ **Shutting down the device**
  - ▶ Long press (> 3 s), after releasing the key the device switches off.




## 11 Display Readings During Measurement

During measurements, the display shows the time, battery charge status, measurement ID and instructions:



During measurement:

Display readings	Function
SUNV1.0.0 Serial:02282222 <b>GT3</b>	<b>Starting up the device</b>


Display readings	Function
	<p><b>Ready to measure mode</b> Shown as start screen for measurements only when ready to measure manually in extended operating mode.</p>
	<p><b>Recording measurement</b> Measurement immediately upon triggering by application of force. Start screen in easy and extended operating mode with automatic ready to measure mode.</p>
	<p><b>Graphical display</b> The measurement result is displayed graphically as a force-time curve. If the display area on the screen permits, the dynamic force and/or the static force are also displayed.</p>

Display readings	Function
	<p><b>Force shown large</b>  Force display in large font  Only in easy operating mode  Displays the peak force <math>F_s</math> or <math>F_d</math> (whichever is greater)</p>
	<p><b>Numerical display</b>  All characteristic values are displayed: the forces <math>F_d</math>, <math>F_s</math>, and <math>F_e</math> as well as the time <math>T_d</math> and the measurement ID.</p>
	<p><b>Display leads to</b></p> <ul style="list-style-type: none"> <li>• Shutting down the device (Long press)</li> <li>• Menu with the device settings (short press), see chapter 13.</li> </ul>

## 12 Measurement

- ① The device must be in the desired mode, see chapter „8 Operating Mode and Ready to Measure Mode“ and chapter „10 Switching On and Off“.

### 12.1 Process Steps – Easy Mode





- ① The measurement results can be displayed repeatedly by short press on the key.

**New measurement:** Can be initiated at any point, at any process step. Simply apply force to the device.

## 12.2 Process Steps – Extended Mode

Measurement results can be displayed once, then a new measurement starts.





## New measurement

At the end of the measurement, when the numerical result is displayed, you can return to the START by a short press on the key.

## Leaving measurement

Manual measurement	Switch to the display of the ready to measure mode Exit with a long press (> 3 s)
Automatic measurement	Switch to measurement recording Exit with a long press (> 3 s)

① The menu opens. From here you can:





- **Shut down the device**
  - ▶ Long press (> 3 s)
- **Access the menu with the settings**
  - ▶ Short Press (< 3 s)

## 12.3 Measuring Process and Display

Measurements with the KMG-T are carried out in several successive process steps, depending on the operating mode and readiness to measure:

Step	Process steps	Display
1	<p>➤ <b>START</b> <b>Manual ready to measure mode</b> <b>extended operation mode,</b> ▶ Press key</p>	
2	<p>➤ <b>START</b> <b>Automatic ready to measure mode</b> <b>in extended operation mode or</b> <b>START easy operation mode</b> ▶ Short press ① The measurement is triggered</p>	

Step	Process steps	Display
3	<p>➔ <b>Perform measurement</b></p> <ul style="list-style-type: none"> <li>▶ Apply force correctly</li> <li>① Once a threshold of 25 N has been exceeded, the force is measured over a period of 5 seconds.</li> <li>① The force curve is displayed during the measurement. The scaling is adjusted to the maximum force that occurs. The ring around the key flashes blue.</li> </ul>	
4	<p>➔ <b>Graphical display of the measurement</b></p> <ul style="list-style-type: none"> <li>① The measurement curve is output at the end of the measurement process. The dynamic and/or static force, if available, is displayed numerically.</li> <li>▶ Press the key.</li> </ul>	

Step	Process steps	Display
5	<p>① <b>This step only takes place in simple operating mode! It is otherwise skipped.</b></p> <p>① Large display of <math>F_d</math> or <math>F_s</math>, depending on which force is greater.</p>	
6	<p>➡ <b>Numerical display of the measurement</b></p> <p>① The following are displayed:</p> <ul style="list-style-type: none"> <li>• <math>F_d</math> dynamic force (if available)</li> <li>• <math>F_s</math> static force (if available)</li> <li>• <math>T_d</math> dynamic time</li> <li>• #ID measurement ID</li> </ul>	

Step	Process steps	Display
7	<p>➔ <b>Next measurement</b></p> <ul style="list-style-type: none"> <li>▶ In the extended mode: short press on the key <ul style="list-style-type: none"> <li>① You reach Step 1 in „manual“ ready to measure mode.</li> <li>① You reach Step 2 in „automatic“ ready to measure mode.</li> </ul> </li> <li>▶ In easy mode: simply apply force</li> </ul>	

## 13 Settings

The setting options can be accessed via the menu in extended mode (long press to enter the menu, short press to continue in the menu).


Menu	Display
<p><b>SHUTDOWN</b> Purpose: Switch off the device or access the options menu <b>Select options 1/5 - 5/5</b> ▶ Continue with a short press on the key</p>	 A rectangular display box with the word "SHUTDOWN" at the top center. Below the text is a power button icon, which consists of a circle with a vertical line extending from the top center.
<p><b>1/5 RECORD</b> <b>Select operation mode</b> ▶ long press to enter the submenu (and back).</p>	 A rectangular display box with the word "RECORD" at the top center. Below the text is an icon of a hand with the index finger pointing upwards, indicating a long press action.

Purpose: In extended mode: Switch on automatic measurement (Auto) or switch off (Manual)

## Menu

## Display

„Manual“ (Modus 1)  
„Automatic“ (Modus 2)




## 2/5 WIRELESS

### Wireless module activate, deactivate

Purpose: Switch on or off the wireless module

- ▶ Long press to enter to submenu (or back):

On  
Off



## Menu

## Display

### 3/5 DELETE


#### Delete data

- ▶ long press to enter to submenu (and back)



Purpose: Delete the memory, when it is full and no more measurements can be recorded.


- Cancel  
(Exit the menu without any changes)
- All Data (Delete all data)



### 4/5 SYSTEM



#### View Information

- ▶ long press to enter to submenu (and back):



**Menu****Display**

<b>SYSTEM 1/5</b> SVN: System version S/N: Serial number WL: D11AA105 CH5: 00000000	 <p>SYSTEM SVN: V1.0.0 S/N: 02222222 WL: D11AA105 CH5: 00000000 1/5</p>
<b>SYSTEM 2/5</b>  Ambient temperature relative humidity	 <p>SYSTEM Temp: 28.2°C 82.8°F Humid: 54.2%rH 2/5</p>
<b>SYSTEM 3/5</b>  Battery voltage Battery current	 <p>SYSTEM Bat U:3.664V Bat I:0mA 3/5</p>

Menu	Display
<p><b>SYSTEM 4/5</b>            Capacity of the measuring memory            Free measuring memory            Used measuring memory            Latest measurement ID</p>	 <p>A rectangular display box with a black border. At the top, the word "SYSTEM" is centered. Below it, the following text is displayed: "Capacity: 372", "Free: 334", "Used: 38", and "Last #ID: 38". At the bottom center, "4/5" is displayed in a black box.</p>
<p><b>SYSTEM 5/5</b>            next calibration date</p>	 <p>A rectangular display box with a black border. At the top, the word "SYSTEM" is centered. Below it, the text "Calib:24-05-24" is displayed. At the bottom center, "5/5" is displayed in a black box.</p>
<p><b>5/5 EXIT</b></p> <p>Exit menu            long press</p>	 <p>A rectangular display box with a black border. At the top, the word "EXIT" is centered. Below it, there is a graphic of a door with an arrow pointing to the right, indicating an exit.</p>

## **14 Calibration at GTE Industrieelektronik**

Your KMG device is in the best hands with us: In our laboratory, the force gauges are loaded and calibrated. As a manufacturer, we know every detail. We calibrate your instrument carefully and accurately. Of course, you will receive a factory calibration certificate for each calibration.

An order form is included in the scope of delivery of your KMG-Lite. To place an order, send us the completed order form together with your device. The KMG Service Bundle offers regular calibrations at favorable conditions.

## 15 KMG-VISION.cloud Service & Evaluation Software

Mit KMG-VISION.cloud can be used to prepare, manage and follow up measurements in accordance with ASR A 1.7. The KMG-VISION.cloud is composed of two components:

- KMG-VISION.cloud Manager is the PC software.
  - KMG-VISION.cloud App is the application for mobile devices such as smartphones with iOS or Android operating systems.
- ① Please note, that the KMG-T can only be used in conjunction with the App if the wireless module is enabled.

The cloud solution allows data to be exchanged between the PC software for managing data in the back office and the App for the testers' mobile devices on site.

Moreover, for further evaluations and documentation the PC software KMG-VISION is available. It also allows measurements to be documented in the form of extensive projects.

## 16 Accessories

As additional accessory for KMG-T we offer a KMG Distance Set, which includes a measurement tripod and distance elements for typical measurement points.

Tripod  
for vertical gates,  
opening height:  
30 cm and 50 cm



Distance elements for  
horizontal gates and  
doors: 30 cm  
and 50 cm



Manual Article No. 305-2310-003-DE-10

## 17 Technical Data

Model	KMG-T
Article No.	305-2301-210
Dimensions of measurement surface	80 mm Ø, Height 50 mm
Dimensions	245 mm x 80 mm x 50 mm (L x W x H)
Weight	0.85 kg
Power supply	Internal Lithium-ion battery
Current	< 20 mA
Battery life	> 100 hours
Interface	USB-C
Memory	372 single measurements
Temperature range	0 ... 40 °C

Relative humidity	20 ... 90 % RH (non-condensing)
Measurement range	25 N ... 2000 N
Measurement accuracy	typ. $\pm 0,4$ % of 2000 N at 20 °C
Maximum measurement error	25 N ... 200 N : $\pm 10$ N 200 N ... 2000 N : 5 %
Spring rate (mechanical filter)	500 N/mm
Rising / falling time	$\leq 5$ ms



Notes





## GTE Industrietechnik GmbH

Helmholtzstr. 21, 38-40  
41747 Viersen | Germany

+49 2162 3703-0 **TEL**

+49 2162 3703-25 **FAX**

[www.kmg-t.de](http://www.kmg-t.de) | [messtechnik@gte.de](mailto:messtechnik@gte.de)

Art.-Nr.: 305-2310-201-EN-10  
January 2024  
Technical changes reserved!